

PRODUCT RECALL

SALTER HAND VACUUM CORDLESS

PROBLEM:
SAFETY ISSUE WITH BS DC ADAPTOR
(UK & IRELAND ONLY)



FAULTY BS DC ADAPTOR (UK & IRELAND ONLY)

We have become aware of a manufacturing defect with a small number of DC Adaptors supplied with the Salter Hand Vacuum Cordless - product images below. **The defect may cause the back of the DC adaptor to come off. The defect affects all UK & Ireland adaptors supplied since: Jan 2020. BS, 3-PIN, DC Adaptor Model Number: TYBSDC1400500**




WHAT YOU SHOULD DO

If you have bought one of these products, stop using it immediately.

For a replacement DC adaptor please submit your details on the 'Product Recall Enquiries' form and our Customer Service Team will issue a replacement charger as soon as available. If you require any further assistance relating to the product recall, please contact our Customer Service Team.

- productsupport@upplc.com
- www.salter.com
- 08081698571



We apologise for any inconvenience caused

Thank you

